





## NOTE:-

All Wrenches must have manufacturers name stamped plainly in the metal.

Steel for wrenches to conform to the following:

OPEN HEARTH STEEL  
Carbon .40 to .50  
Phosphorus not over .04  
Sulphur not over .04  
Manganese about .40

Wrenches must be properly tempered and free from water cracks.  
Jaws to be milled out to insure accuracy.




**STANDARD  
TRACK WRENCHES**  
PHILA., AUGUST, 1905.

**61750-G**  
REVISED: 35


FEB. 1906.  
JUNE 1908.  
JULY 1911.  
FEB. 1914.  
OCT. 1915.  
MAY 1916.  
JAN. 1918.

Correct



Asst. Engr. W.

Approved



Engineer W.

Approved



General Manager