



NOTE:-

All Spiking Hammers must have manufacturer's name and letters "PS" in keystone stamped plainly in the metal.

Spiking Hammers must be properly tempered and free from water cracks and steel must conform to the following:-

CRUCIBLE STEEL

Carbon	.60 to .75
Phosphorus	.04 or under
Sulphur	.04 or under
Manganese	about .40

